


Accurate Hot Selling HQT-4180 Exam Dumps 2022 Newly Released [Q12-Q30]



Accurate Hot Selling HQT-4180 Exam Dumps 2022 Newly Released
Get 100% Authentic Hitachi HQT-4180 Dumps with Correct Answers

Q12. What are two functions of the LAN Blade in the VSP Midrange family? (Choose two.)

- * It provides the LAN connection to the file module.
- * It provides the maintenance port connecting to the MPC.
- * It provides the iSCSI connection to the servers.
- * It provides the management port connecting to the customer LAN.

Q13. You need to replace a broken disk drive on a VSP G700.

What are two prerequisites? (Choose two.)

- * You must use the Replace button in the Maintenance Utility before removing the drive.
- * You must wear a wrist strap for ESD protection.
- * The red LED on the drive must be lit.
- * The Drive Box where the drive is located must be powered down.

Q14. Which program is used to perform the 'New Installation' procedure on a VSP midrange system?

- * MPC
- * Webconsole
- * GUM
- * BECK

Q15. Which three RAID configurations are supported by VSP Midrange systems? (Choose three.)

- * 2D + 2D
- * 4D + 1P
- * 7D + 1P
- * 8D + 1P
- * 10D + 2P

Q16. Which two reconfiguration activities are performed without interrupting host access on a VSP Gx00 system? (Choose two.)

Choose 2 answers

- * adding a DKB
- * adding a DB60 drive tray
- * upgrading from G200 to G800
- * upgrading from G200 to G600

Q17. What is the maximum size of a basic volume carved out from an internal parity group on a VSP E590 system?

- * 1 TB
- * 2.99 TB
- * 65 TB
- * 128 TB

Q18. Which manual should be used when performing maintenance actions on VSP midrange storage systems?

- * Product Documentation Library
- * Service Guide
- * Administrator Guide
- * Maintenance Manual

Q19. A customer wants to upgrade a VSP G700 to 512 GB RAM capacity.

What is the valid CFM configuration?

- * two BM35 per controller
- * two BM45 per controller
- * one BM45 per controller
- * two BM35 per system

Q20. Which tool do you use to install license keys on a VSP G370 system?

- * HSA Embedded
- * MPC Software
- * Storage Navigator
- * Maintenance Utility

Q21. Which tool is used for the remote monitoring of a VSP N800 system?

- * Hitachi Remote Ops SVP Agent
- * Hitachi Remote Ops Monitor Agent
- * MPC Software
- * Hitachi Performance Monitor

Q22. What are two consequences when a "New Installation" procedure is performed on a VSP Midrange system? (Choose two.)

- * The SVP drive is formatted.
- * The MPC software is updated.
- * All the data on RAID groups is lost.
- * The license keys are deleted.

Q23. You have to perform a firmware update containing new code for DKCMain, CHBs and drives on a VSP G900.

What are two requirements? (Choose two.)

- * The CHBs must be updated first.
- * The Microprocessor utilization should be below 50%.
- * The Cache Write Pending rate should be below 30%.
- * There should be no sparing processes running in the background.

Q24. The SVP of a VSP G900 system failed and you have been asked to replace it.

Which two items must be available to perform the replacement? (Choose two.)

- * the iso file with the correct version of Hitachi Ops Center
- * the iso file with the correct version of the Windows operating system
- * the microcode iso file with the correct software versions
- * the Hitachi Remote Ops Monitor Agent iso file

Q25. A customer wants to change a production RAID Group from RAID 5 (7D+1P) to RAID 6 (6D + 2P) on a VSP G700 during normal operations. They have just unmapped the LUNs from the channel ports.

What needs to be performed next?

- * The RAID level must be changed in Storage Navigator.
- * The RAID level must be changed in the SVP Maintenance window.
- * The RAID 5 Group must be put into DRU mode in Storage Navigator.
- * The RAID Group must be deleted.

Dumps of HQT-4180 Cover all the requirements of the Real Exam:

<https://www.topexamcollection.com/HQT-4180-vce-collection.html>